

000000" 8904E 9510




FIG 1

The image shows a screenshot of a software dialog box titled "Setup and Hold". The dialog box contains a warning message: "Warning: When the setup and hold specification for a label is changed, this impacts all other labels that include the same channels." Below the warning, there are two radio buttons: "All bits" (selected) and "Individual bits". Under "All bits", there are fields for "Bit:" (set to 0), "Setup:" (set to 2.500 ns), and "Hold:" (set to 0 s). Each field has a small up/down arrow icon. At the bottom of the dialog box, there are two buttons: "Ok" and "Cancel".

210

FIG 2







FIG. 3





008080" 8904E960



008080" 8904E960




FIG. 10




FIG. 11




FIG. 12